ECS/EMD Configuration Change Request					Page 1 of	f	Page(s)		
1. Originator	2. Log Date:	3. CCR #:		4. Rev	: 5. Tel:		6. Rm #:	7. Org.	
Henry Baez	12/01/2004 04		0655		301-925-1025		3108G	COTS HW	
8. CCR Title: Release IBM IY58673 Patch for SMC firewall.									
9. Originator Signature/Date			10. C	10. Class 11. Type: 12. Need Date: 12			: 12/2/2004		
Henry Baez /s/ 11/30/2004			II		CCR				
13. CCR Sponsor Signature/Date			14. Category		of Change:	15. Priority: (If "Emergency" fill in Block 27).			
Pamela Johnson /s/ 11/30/2004				Patch/TE		Routine			
3				7. Schedule 18. Cl(s mpact:		Affected:			
19. Release Affected by this Change: 20. Date due			co Customer: 21. Estimated Converse None - Under 100						
22. Source Reference: ⊠NCR (attach) □Action Item □Tech Ref. □GSFC □Other: 41469									
23. Problem: (use additional Sheets if necessary) The SMC had an error on Oct. 29, "SOFTWARE PROGRAM ABNORMALLY TERMINATED". This produced a core dump. The firewall did not crashed.									
24. Proposed Solution: (use additional sheets if necessary) IBM reports a problem with use of the netstat command in AIX 5.1. IBM says it should not stop or crash the AIX OS. At the same time IBM has put out a fix, IY58637, and highly recommends you install it. IY59637 is a group of updated file sets. This patch was tested in VATC for three weeks and PVC for to two weeks. No problem was found, load test where carried out between PVC and VATC. The file is on lemmings, netstatcore.tar, cksum numbers 2967102334 47349760.									
25. Alternate Solution: (use additional sheets if necessary) None.									
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) IBM says this should not cause a crash or stoppage, not that it will not cause a crash. Additional errors, core files, might cause failure of SMC firewall. SMC firewall is main DNS server for ecs.nasa.gov domain.									
27. Justification for Emergency (If Block 15 is "Emergency"):									
28. Site(s) Affected: DF DVC VATC EDC GSFC LaRC NSIDC SMC AK JPL DEOC DIDG Test Cell Other									
29. Board Comments:				30.	Work Assigned T	o:	31. CCR C	Closed Date:	
22 SCDV CCD Chair (Simo	//Data):	ionesitio A	I	A == 10	om Disservin	1 / / /	ith draw -	4/E0DIO EDD	
32. SCDV CCB Chair (Sign Byron V. Peters /s/ 12/2/0		isposition: Ar Fv	vd/ECS	Арр/С	om. Disapproved	a VV	illiuraw FW	u/EODIO EKB	
33. EDF CCB Chair (Sign/E	Date): D	isposition: Ap		App/Co	om. Disapproved	W b	ithdraw Fwo	d/ESDIS ERB	
		Fv	vd/ECS						
34. ECS CCB Chair (Sign/D	Date): Dis	sposition: App	proved	App/Co	m. Disapproved	W	ithdraw Fw	d/ESDIS ERB	

CM01JA00 Revised 10/2/03 ECS/EDF/SCDV

Fwd/ESDIS

ADDITIONAL SHEET

CCR #: 04-0655 Rev: Originator: Henry Baez

Telephone: 301-925-1025 **Office:** 3108G

Title of Change: IRelease IBM IY58673 Patch for SMC firewall.

For VATC and PVC firewall:

Create a new directory under /tmp. Call it '/tmp/fixes/netcore'. Change directory to /tmp/fixes/netcore. #mkdir /tmp/fixes/netcore <enter>

#cd /tmp/fixes/netcore <enter>

The file name is netstatcore.tar and need to check that the file is good with the AIX command cksum as follows:

cksum netstatcore.tar

The results are shown below:

2967102334 47349760 netstatcore.tar

Next un-tar the file as follows:

tar -xvf netstatcore.tar

Now type the following command:

#inutoc . <enter>

This will build the '.toc' file the installation program needs. Start the SMIT program with the following command:

#smit <enter>

The first menu heading will read:

Software Installation and Maintenance

Click on the box labeled as follows:

Install and Upgrade Software

Click on the box labeled as follows:

Update Installed Softeware to Latest Level (Update All)

A new menu will pop up. It will display the message/question "INPUT device / directory". Write in the directory path '/tmp/ fixes/netcore' where the files are located. Click on 'OK' button.

Next menu will pop up. Take all the defaults. Click on 'OK' button to continue.

A new dialog box will display 'Are You Sure', click on 'OK' button to start installing the file sets. Estimated installation time is less then 15 minutes. You will have to reboot the firewall.

CM01AJA00 Revised 10/2/03 ECS/EMD